

Recorded by Lisa Mausolf

Organization Lexington Historical Commission

Date (month/year) April-May 2000

Town Lexington

Place (neighborhood or village) Upper Meriam Hill

Address 2 Berwick Road

Historic Name William & Marcia Nash House

Uses: Present Residential

Original Residential

Date of Construction 1912

Source Lexington Valuation Lists

Style/Form Craftsman/Four Square

Architect/Builder unknown

Exterior Material:

Foundation stucco

Wall/Trim stucco/wood

Roof asphalt shingle

Outbuildings/Secondary Structures

garage

Major Alterations (with dates) none

Condition good

Moved no ses Date

Acreage 14,210 SF

Setting early 20th century residential neighborhood

BUILDING FORM (2 Berwick Road)

ARCHITECTURAL DESCRIPTION

Describe architectural features. Evaluate the characteristics of the building in terms of other buildings within the community.

The house at 2 Berwick Road is a 2 1/2-story, stuccoed dwelling that is capped by an asphalt-shingled, hip roof with projecting eaves. The three-bay facade is partially fronted by a single-story porch that extends from the center entrance and wraps around the west elevation, terminating at the two-story hip-roofed wing offset to the northwest. The porch is supported by wide stuccoed posts which are capped by pairs of brackets. A low pediment marks the location of the entrance. Sheltered by the porch, the entrance contains a wooden door with 3 x 4-lights over four recessed panels. The door is framed by partial sidelights. Also sheltered by the porch is a large picture window with multi-light upper band. To the east of the entrance and outside the porch, there is a bay window on the first floor containing three 6/1 windows. The second floor of the facade has a central 6/1 window flanked by 4/1 windows, with a pair of 6/1 windows on either side. Centered on the front roof slope is a hip dormer with two small 6/1 windows.

The rear wing displays two cutaway corners on the second floor with 4/1 windows and a set of four 6/1 windows on the first floor. The east side of the house is four bays deep and displays a variety of window sizes, predominantly 6/1 and 1/1 with a geometric elevated window on the first floor. The back porch on this elevation is supported by plain posts on a stuccoed wall.

The level 14,210 square foot is largely wooded. A stone wall marks the rear property line and a hedge runs along Hayes Avenue. A paved driveway extends along the east side of the house. Behind the house is a single-story, stuccoed, hip-roofed garage with 6/1 windows.

HISTORICAL NARRATIVE

Describe the history of the building. Explain its associations with local (or state) history. Include uses of the building and the role(s) the owners/occupants played within the community.

It appears that this house was constructed in 1912 for William and Marcia Nash on Lot 58, Part A of the Oakmount Subdivision. The 1912 Lexington Valuation List assesses the Nashes, with an address of 19 Congress Street in Boston, for a house valued at \$5000. The following year the assessment had increased to \$10,000, suggesting the completion of the house. Directories indicate that William Nash was employed as a bookkeeper.

By 1934 the house was being occupied by Miss Cora Jackson. About 1935 the address of the house was renumbered from #1 to #2 Berwick Road. Guy and Marjorie Reed acquired the house about 1950 and remained here until at least 1970.

BIBLIOGRAPHY and/or REFERENCES

Lexington Assessors Records.
Lexington Directories, various dates.
Lexington Valuation Lists, various dates.

Recommended for listing in the National Register of Historic Places. If checked, you must attached a completed National Register Criteria Statement form.